

## Optické adaptéry LC Duplex

### Prehľad

- Optický adaptér LC Duplex je spojovacím prvkom a slúži k prepojeniu optického pigtailu a adaptéra



OS2



OS2/APC




OM1/OM2



OM3



OM4



| Parameters                   | Value                      |
|------------------------------|----------------------------|
| Typical Insertion Loss       | $\leq 0.1$ dB              |
| Max Insertion Loss           | $\leq 0.2$ dB              |
| Durability(500 Mating Times) | $\Delta I. L. \leq 0.2$ dB |
| Operating Temperature        | -40°C ~ +75°C              |
| Storage Temperature          | -40°C ~ +85°C              |

